

Varilux® LIBERTY™

80/85mm
77/82mm





FIG. A. Fitting heights positioned too low can result in loss of useable reading area—one of the most common causes of non-adapts. To ensure proper positioning, place fitting cross marks over the midpupil. Check to be sure that the vertical fitting height is a minimum of 18 mm.

Minimum suggested fitting height for Varilux Liberty is 18 mm.
LVAE200184
0666CP

 © 2004 Essilor of America, Inc.
Varilux is a registered trademark of Essilor International, S.A.
Liberty is a trademark of Essilor of America, Inc.

